## Fire Risk Assessment

Property assessed: 1-43, 101, 102 (no 13) Linacre House Heathmere Drive


House Heathmere Drive Birmingham B37 5EW

Client: Solihull Community Housing

UPRN: 123350000A

Property Classification: Level 1

Document Print Date: 16/12/2020



FRA Inspection Date: 04/11/2020
FRA Issued to Client: 16/12/2020
FRA valid to: 16/12/2021
FRA completed by: Savills (UK) Ltd,

33 Margaret Street, London W1G 0JD

T: 020 7409 8737

E: fireriskhousing@savills.com



## Contents



- **Executive Summary** 1
  - 1.1 Compliance and Risk Record
  - 1.2 **Recommendation Summary**
  - 1.3 **Evacuation Strategy**
- **Action Plan** 2
  - 2.1 Recommendations from this Assessment
- **Introduction and Scope** 3
  - 3.1 Limitations
  - 3.2 Legislation
  - 3.3 Risk Level
  - 3.4 **Recommendation Priorities**
- **Property Details** 4
- **FRA Questionnaire** 5
- 6 **BAFE Certificate**

Please Note - The Action Plan within this report will update to reflect the status of each recommendation as at the date on which the report is generated. Please refer to the Document Print Date on the cover page.

# **1** Executive Summary



### Compliance and Risk Record

Property Classification	Level 1
BAFE SP205 -1 Certificate Number	Refer to Master Property List
Responsible Person	Solihull Community Housing
Assessment Completed by	Neil Sturdy
Assessment Checked by	John Herbison
Date of inspection	04/11/2020
Date of Assessment Issue to Client	16/12/2020

Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at this property is:	Medium
Taking into account the nature of the property and occupants, as well as fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:	Moderate Harm
The derived assessment risk rating of the property is:	Moderate
On satisfactory completion of all remedial works the risk rating of this property may be reduced to:	Tolerable

	Recommended Reassessment Date	16/12/2021	
--	-------------------------------	------------	--



### **1.2** Recommendation Summary

Priority	Number of recommendations not complete			
	From previous assessments	At time of assessment	At report print date	
U	0	0	0	
Α	0	3	3	
В	0	2	2	
С	0	3	3	
R	0	1	1	
Man1	0	1	1	
Man2	0	22	22	

Note: See section 3.4 for the timescales associated with each priority in the table above.

## 1.3 Evacuation Strategy

Evacuation strategy for this property at time of assessment	Stay Put
Notes	The premises is purpose-built with an adequate standard of compartmentation. The current Stay Put evacuation strategy is considered appropriate.
Recommended evacuation strategy for this property	Stay Put

## 2 Action Plan



### Recommendations from this Assessment

Details		Comments/recommendations	Photo
Question	Q.13	Comment: No information was available on site to	
Section	Limiting Fire Spread	confirm if the external wall insulation system met the requirements of the Building Regulations with	
Action ID	572677	regards to limited combustibility and surface fire spread requirements. Advised by management that the wall insulation is mineral wool insulation fixed directly to the wall of the block with a render finish, no information was available to confirm this.	
Quantity - Known - Potential	N/A N/A	Recommendation: Management should confirm that the external wall insulation system meets Building Regulations requirements with regards to limited combustibility and surface fire spread properties.	
Priority	Man1	Due Date: 16/01/2021	
Question	L.2	Comment: Fire-rated flat entrance doors and frames	
Section	Flat Entrance/Residents' Bedroom/Bedsit Doors	appear to be in good condition except for:- Flat entrance doors 4 & 12 appear damaged.	
Action ID	572664		
Quantity - Known - Potential	2	Recommendation: Doors and frames as noted should be replaced with FD30S self-closing fire door sets, installed strictly in accordance with the manufacturer's test certification.	
Priority	Α	Due Date: 16/03/2021 Client Status: Not Complete	
Question Section	M.4  Common Area Fire  Doors	Comment: Fanlights/side panels to common area fire doors appear to be the original Georgian-wired fire rated. Current regulation would require glazing to the stairway and accommodation lobby door side panels to be 60-	
Action ID	572669	minute integrity and insulation below 1100mm. The side panel on the 1st-floor to flats 4 $\&$ 5 is damaged.	o [
Quantity - Known - Potential	1	Recommendation: 60-minute fire-resisting integrity and insulation glazing/material should be installed in the side panels to common area fire doors as noted (side panel on the 1st-floor to flats $4\ 6\ 5$ ).	
Priority	A	Due Date: 16/03/2021	
Question	M.5	Comment: Not all common area fire doors are fitted	
Section	Common Area Fire Doors	with adequate self-closing devices where required - The following doors are not fully closing into the frames with the aid of the self-closing device, doors to the	
Action ID	572670	accommodation lobbies to flats 40 & 43 and 28 & 31.	
Quantity - Known - Potential	2 2	Recommendation: The self-closing device should be repaired or an effective self-closing device should be fitted to the doors as noted.	
Priority	A	Due Date: 16/03/2021	



Question	K.7	Comment: It could not be ascertained whether the electrical access control systems fitted to escape route	
Section	Means of Escape	doors/gates are provided with override facilities and/or	
Action ID	572660	are designed to 'fail safe' on power failure.	
Quantity	•	Recommendation: Management should confirm that the secure door entry system continues to operate in the	
- Known	0	event of a power failure, or fails safe to open. If not, an	
- Potential	2	emergency override facility will be required.	
Priority	Man2	Due Date: 16/03/2021	
Question	K.14	Comment: The accommodation lobby with the bin chute	
Section	Means of Escape	room has a replacement uPVC fixed shut window. The stairs and the other lobby are provided with adequate	
Action ID	572662	permanent or manually operated ventilation openings for the control of smoke, no ventilation provided to the stair lobby. A PV is provided to the bin chute room and to the head of the stairs. The vent at the head of the stair requires cleaning as the vents are partially blocked with dust/dirt.	
Quantity		Recommendation: The smoke vent noted to the head of	
- Known	1	the stairs should be cleaned.	
- Potential	1		
Priority	Man2	Due Date: 16/03/2021 Client Status: Not Complete	
Question	K.16	Comment: There was no information available regarding	
Section	Means of Escape	arrangements in the building for means of escape for people with disabilities.	
Action ID	572663		
Quantity		Recommendation: Management should encourage	
- Known	N/A	residents of this General Needs property to contact the building manager if they require assistance in developing	
- Potential	N/A	a personal emergency evacuation plan (PEEP) or other fire safety advice. This could be achieved by adding a contact reference for assistance to the fire action notices for the premises, by providing additional separate notices containing the information or making direct contact with residents via letter, flyer or website for example.	No image available
Priority	Man2	Due Date: 16/03/2021	
Question	L.6	Comment: No access was possible to any of the flat	
Section	Flat Entrance/Residents' Bedroom/Bedsit Doors	entrance doors to confirm that they are fitted with adequate self-closing devices.	
Action ID	572666		
Quantity		Recommendation: Management should establish an	No image available
- Known	0	ongoing rolling programme of checks to all flat entrance	
- Potential	44	doors to confirm that self-closers are fitted and remain effective.	
Priority		Due Date: 16/03/2021	



Question	L.7	Comment: There was no	access possible to any of the	
Section	Flat Entrance/Residents' Bedroom/Bedsit Doors	flat entrance doors to confirm that they are fitted with intumescent strips and cold smoke seals.		
Action ID	572667			
Quantity - Known - Potential	0 44	ongoing rolling program	agement should establish an nme of checks to all flat entrance rips and seals are fitted and	No image available
Priority	Man2	Due Date: 16/03/2021	Client Status: Not Complete	
Question	P.5		as possible to any of the flats to	
Section	Means of Giving Warning in Case of Fire	confirm that they are fitted system.	ted with an adequate smoke alarm	
Action ID	572672			
Quantity - Known - Potential	0 44	Recommendation: All flats should be checked to confirm provision and working condition of at least Grade D LD3 smoke alarm systems to BS 5839-6:2019. An ongoing rolling programme of checks should be confirmed to be in place. If new systems are required to be installed these should be to Grade D1 LD2 standard.		No image available
Priority	Man2	Due Date: 16/03/2021	Client Status: Not Complete	
Question	Q.2	•	ossible to sample inspect the	
Section	Limiting Fire Spread		without causing damage or nere appear to be flush floor	
Action ID	572673	to ceiling riser in the bin chute rooms and sealed false ceilings throughout the common areas. There are also boxed-in services ducts within the stairway, lift lobbies and floor to ceiling service risers in the accommodation lobbies (x 3) that are screwed shut of unknown construction. It is not possible to check compartmentation behind without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and accommodation lobbies.		
Quantity - Known - Potential	0	Recommendation: Management should undertake an intrusive inspection of the hidden voids noted to confirm/ ensure that compartmentation within is adequate.		
Priority	Man2	Due Date: 16/03/2021	Client Status: Not Complete	



Section Limiting Fire Spread  Action ID  Ouantity - Known O - Potential  Action ID  Triority Man2  Comment: It was not possible to sample inspect the hidden voids identified without causing damage or requiring opening up. There appear to be flush floor to celling review of series in the accommodation lobbles (x 3) that are screwed shut of unknown construction. It is not possible to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles.  Recommendation: A sample check should be made of the boxed-in services without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles.  Priority  Man2  Due Date: 16/03/2021  Client Status: Not Complete  Comment: It was not possible to sample inspect the hidden voids identified without causing damage or requiring pening up. There appear to be flush floor to celling retent bein-chute rooms and saseled false cellings throughout the common areas. There are also boxed-in services ducts within the stainway, lift lobbles and floor to celling serve sheet in the accommodation lobbles (S) that are screwed shut of unknown construction, It is not possible to check the fire rating of the walls between the bin-chute rooms and saseled false cellings throughout the common areas. There are also boxed-in services ducts within the stainway, lift lobbles and floor to celling serve sheet in the accommodation lobbles (S) that are screwed shut of unknown construction, It is not possible to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles.  Recommendation: Management should undertake intrusive checks to ensure/confirm the walls between the bin-chute rooms and accommodation lobbles.  Recommendation: Management should undertake intrusive checks to ensure/confirm the walls between the bin-chute rooms and accommodation lobbles.  Recommendation: Management should undertake intrusive checks to ensure/confirm the walls between the bin-chute rooms and				
Action ID 572674 requiring opening up. There appear to be flush floor to celling ires in the bin chuter comas and sealed false cellings throughout the common areas. There are also boxed in services ducts within the stainway, tift tobbles and floor to celling service risers in the accommodation lobbles (x) 5) that are screwed shut of unknown construction. It is not possible to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles (x) 5) that are screwed shut of unknown construction. It is not possible to check compartmentation behind without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles.  Priority Man2 Due Date: 16/03/2021 Client Status: Not Complete  Question Q.2  Comment: It was not possible to sample inspect the hidden voids identified without causing damage or requiring opening up. There appear to be flush floor to celling isser in the bin chute rooms and sealed false cellings stroughout the common areas. There are also boxed-in services ducts within the stainway, lift lobbles and floor to celling service risers in the accommodation lobbles (x) 3) that are screwed shut of unknown construction. It is not possible to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles (x) 3) that are screwed shut of unknown construction. It is not possible to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles (x) that of unknown construction. It is not possible to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles (x) that of unknown construction. It is not possible to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles (x) that of unknown construction it is not possible to check the fire rating of the walls between the bin-chute rooms and accommodation lobbles (x) that of unknown construction it is not possible to check the fire rating of the walls be				
- Known O of the boxed-in services ductwork to confirm that the construction is adequately fire resisting and that compartmentation behind has not been compromised at services penetrations etc.  Priority Man2 Due Date: 16/03/2021 Client Status: Not Complete  Question Q.2 Comment: It was not possible to sample inspect the hidden voids identified without causing damage or requiring opening up. There appear to be flush floor to celling ifier in the bin chute rooms and sealed false cellings throughout the common areas. There are also boxed-in services ducts within the stainway, lift lobbies and floor to celling service risers in the accommodation lobbies (x 3) that are screwed shut of unknown construction. It is not possible to check compartmentation behind without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and accommodation lobbies.  Quantity Recommendation: Management should undertake intrusive checks to ensure/confirm the walls between the bin chute rooms and accommodation lobby is appropriately fire rated (120-minute standard - current regulations)  Priority Man2 Due Date: 16/03/2021 Client Status: Not Complete  Priority Man2 Due Date: 16/03/2021 Client Status: Not Complete  Cuantity According to the service cupboards on the 10th, 7th, 4th and 1st-floors appear to be adequately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors and 1st-floors. Not all dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th and 1st-floors. Not all dry-riser server inspected.  Quantity Recommendation: Management should check within services risers cupboards not inspected to confirm that they are adequately fire-stopped.			requiring opening up. There appear to be flush floor to ceiling riser in the bin chute rooms and sealed false ceilings throughout the common areas. There are also boxed-in services ducts within the stairway, lift lobbies and floor to ceiling service risers in the accommodation lobbies (x 3) that are screwed shut of unknown construction. It is not possible to check compartmentation behind without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and	
Question         Q2         Comment: It was not possible to sample inspect the hidden voids identified without causing damage or requiring opening up. There appear to be flush floor to celling riser in the bin chute rooms and sealed false ceilings throughout the common areas. There are also boxed-in services ducts within the stairway, lift tobbies and floor to celling service risers in the accommodation lobbies (x 3) that are screwed shut of unknown construction. It is not possible to check compartmentation behind without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and accommodation lobbies.           Quantity	- Known		of the boxed-in services ductwork to confirm that the construction is adequately fire resisting and that compartmentation behind has not been compromised at	
Action ID   S72691   S72692	Priority	Man2	Due Date: 16/03/2021	
Action ID 572691 requiring opening up. There appear to be flush floor to ceiling riser in the bin chute rooms and sealed false ceilings throughout the common areas. There are also boxed-in services ducts within the stairway, lift lobbies and floor to ceiling service risers in the accommodation lobbies (x 3) that are screwed shut of unknown construction. It is not possible to check compartmentation behind without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and accommodation lobbies.  Quantity  - Known  - Potential  Question  Q.3  Section  Limiting Fire Spread  Action ID  572676  Action ID  Find Ty  Recommendation: Management should undertake intrusive checks to ensure/confirm the walls between the bin-chute rooms and accommodation lobby is appropriately fire rated (120-minute standard - current regulations)  Priority  Man2  Due Date: 16/03/2021  Client Status: Not Complete  Comment: The services riser/cupboards sampled did not appear to be adequately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors and by flat 101 do not appear appropriately fire stopped.  The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th and 1st-floors. Not all dry-risers were inspected.  Quantity  - Known  O  - Potential  11  Recommendation: Management should check within services risers cupboards not inspected to confirm that they are adequately fire-stopped.	Question	Q.2		
Action ID  Action ID  S72691  to ceiling riser in the bin chute rooms and sealed false ceilings throughout the common areas. There are also boxed-in services ducts within the stairway, lift lobbies and floor to ceiling service risers in the accommodation lobbies (x 3) that are screwed shut of unknown construction. It is not possible to check compartmentation behind without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and accommodation lobbies.  Recommendation: Management should undertake intrusive checks to ensure/confirm the walls between the bin chute rooms and accommodation lobby is appropriately fire rated (120-minute standard - current regulations)  Priority  Man2  Due Date: 16/03/2021  Client Status: Not Complete  Comment: The services riser/cupboards sampled did not appear to be adequately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors and by flat 101 do not appear appropriately fire stopped.  Action ID  S72676  Recommendation: Management should check within services risers cupboards not inspected to confirm that they are adequately fire-stopped.	Section	Limiting Fire Spread		
- Known 0 intrusive checks to ensure/confirm the walls between the bin chute rooms and accommodation lobby is appropriately fire rated (120-minute standard - current regulations)  Priority Man2 Due Date: 16/03/2021 Client Status: Not Complete  Question Q.3 Comment: The services riser/cupboards sampled did not appear to be adequately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors and by flat 101 do not appear appropriately fire stopped. The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th and 1st-floors. Not all dry-risers were inspected.  Quantity - Known 0 - Potential 11  Recommendation: Management should check within services risers cupboards not inspected to confirm that they are adequately fire-stopped.	Action ID	572691	false ceilings throughout the common areas. There are also boxed-in services ducts within the stairway, lift lobbies and floor to ceiling service risers in the accommodation lobbies (x 3) that are screwed shut of unknown construction. It is not possible to check compartmentation behind without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and	No image available
Question Q.3  Comment: The services riser/cupboards sampled did not appear to be adequately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors and by flat 101 do not appear appropriately fire stopped. The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th and 1st-floors. Not all dry-risers were inspected.  Quantity  - Known 0  - Potential 11  Comment: The services riser/cupboards sampled did not appear appropriately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors and by flat 101 do not appear appropriately fire stopped.  Recommendation: Management should check within services risers cupboards not inspected to confirm that they are adequately fire-stopped.	- Known		intrusive checks to ensure/confirm the walls between the bin chute rooms and accommodation lobby is appropriately fire rated (120-minute standard - current	
Section Limiting Fire Spread  appear to be adequately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors and by flat 101 do not appear appropriately fire stopped. The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th and 1st-floors. Not all dry-risers were inspected.  Quantity  - Known 0  - Potential 11   appear to be adequately fire-stopped. Sample inspected service sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors and by flat 101 do not appear appropriately fire stopped.  Recommendation: Management should check within services risers cupboards not inspected to confirm that they are adequately fire-stopped.	Priority	Man2	Due Date: 16/03/2021	
Section Limiting Fire Spread  service cupboards on the 10th, 7th, 4th and 1st-floors and by flat 101 do not appear appropriately fire stopped. The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th and 1st-floors. Not all dry-risers were inspected.  Quantity  - Known 0  - Potential 11  Recommendation: Management should check within services risers cupboards not inspected to confirm that they are adequately fire-stopped.	Question	Q.3	· · · · · · · · · · · · · · · · · · ·	
The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th and 1st-floors. Not all dry-risers were inspected.  Quantity  - Known 0  - Potential 11  The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th and 1st-floors. Not all dry-risers were inspected.  Recommendation: Management should check within services risers cupboards not inspected to confirm that they are adequately fire-stopped.	Section	Limiting Fire Spread		
- Known 0 services risers cupboards not inspected to confirm that they are adequately fire-stopped.	Action ID	572676	The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th	
Priority Man2 Due Date: 16/03/2021 Client Status: Not Complete	- Known		services risers cupboards not inspected to confirm that	
	Priority	Man2	Due Date: 16/03/2021	



Question	T.3	Comment: No suitable record of the fire safety	
Section	Procedures and Arrangements	arrangements for the building was available for inspection during the inspection.	
Action ID	572678		
Quantity - Known - Potential	N/A N/A	Recommendation: Management should confirm/ ensure that a suitable documentary record of the fire safety arrangements for the building is held within the building or at a central location. This should cover all arrangements for the effective planning, organisation, control, monitoring and review of the preventative and protective measures in place and should include a plan for responding in the immediate aftermath of a fire incident.	No image available
Priority	Man2	Due Date: 16/03/2021 Client Status: Not Complete	
Question	T.10	Comment: It is not known if liaison with the local Fire and	
Section	Procedures and Arrangements	Rescue Service takes place.	
Action ID	572679		
Quantity - Known - Potential	N/A N/A	Recommendation: Management should confirm/ensure appropriate liaison takes place with the local Fire and Rescue Service and that familiarisation visits are carried out. Records of all engagement should be kept on-site or in a central database.	No image available
Priority	Man2	Due Date: 16/03/2021	
Question	T.11	Comment: It is not known if routine fire safety checks are	
Section	Procedures and Arrangements	being carried out.	
Action ID	572680		N. 1
Quantity - Known - Potential	N/A N/A	Recommendation: Management should confirm/ensure that routine in-house fire safety checks are carried out on a regular basis (daily or weekly depending on building usage) and records kept on-site or in a central database.	No image available
Priority	Man2	Due Date: 16/03/2021 Client Status: Not Complete	
Question	V.1	Comment: No evidence was available on-site to confirm	
Section	Testing and Maintenance	regular inspection, testing and servicing of the system is being carried out.	
Action ID	572681		
Quantity - Known - Potential	N/A N/A	Recommendation: Management should confirm/ensure that the Grade A/Part 1 common area fire detection and alarm system is tested weekly and serviced six monthly in accordance with BS 5839-1 and records kept on-site or in a central database.	No image available
Priority	Man2	Due Date: 16/03/2021	



Question	V.2	Comment: No evidence was available on-site to confirm	
Section	Testing and Maintenance	regular inspection, testing and servicing of the system is being carried out.	
Action ID	572682		
Quantity - Known - Potential	N/A N/A	Recommendation: Management should confirm/ensure that the common area emergency lighting system is tested monthly and serviced annually in accordance with BS 5266-8:2004 and records kept on-site or in a central database.	No image available
Priority	Man2	Due Date: 16/03/2021	
Question	V.5	Comment: No evidence was available on-site to confirm	
Section	Testing and Maintenance	regular inspection, testing and servicing of the system is being carried out.	
Action ID	572683		
Quantity - Known - Potential	N/A N/A	Recommendation: Management should confirm/ensure that the lightning protection system is tested and serviced annually in accordance with BS EN 62305 and records kept on-site or in a central database.	No image available
Priority	Man2	Due Date: 16/03/2021	
Question	V.8	Comment: No evidence was available on-site to confirm	
Section	Testing and Maintenance	regular inspection, testing and servicing of the system is being carried out.	
Action ID	572684		
Quantity - Known - Potential Priority	N/A N/A Man2	Recommendation: Management should confirm/ensure that the access control system is inspected, tested and serviced in accordance with relevant guidance and records kept on-site or in a central database.  Due Date: 16/03/2021 Client Status: Not Complete	No image available
Question	V.9	Comment: No evidence was available on-site to confirm	
Section	Testing and Maintenance	regular inspection, testing and servicing of the system is being carried out.	
Action ID	572685		
Quantity - Known - Potential	N/A N/A	Recommendation: Management should confirm/ensure that the drop key override switch facilities for Fire and Rescue Service access are inspected, tested and serviced in accordance with relevant guidance and records kept on-site or in a central database.	No image available
Priority	Man2	Due Date: 16/03/2021	
Question	V.10	Comment: No evidence was available on-site to confirm	
Section	Testing and Maintenance	regular inspection, testing and servicing of the system is being carried out.	
Action ID	572686		Na income and 1.1
Quantity - Known - Potential	N/A N/A	Recommendation: Management should confirm/ensure that lifts are inspected, tested and serviced in accordance with the relevant legislation and guidance and records kept on-site or in a central database.	No image available
Priority	Man2	Due Date: 16/03/2021	



Question	V.11	Comment: No evidence was available on-site to confirm regular inspection, testing and servicing of the system is	
Section	Testing and Maintenance	being carried out.	
Action ID	572687		
Quantity		Recommendation: Management should confirm/ensure	No image available
- Known	N/A	that the sprinkler system is inspected, tested and serviced in accordance with relevant guidance and records kept	
- Potential	N/A	on-site or in a central database.	
Priority	Man2	Due Date: 16/03/2021	
Question	W.1	Comment: No log book was available on site during the	
Section	Records	inspection.	
Action ID	572688		
Quantity		Recommendation: Management should confirm/ensure	No image available
- Known	N/A	that a fire safety log book is provided to enable recording	<u>-</u>
- Potential	N/A	as required of all relevant fire safety events such as fire drills, routine checks, Fire and Rescue Service visits, fire	
		safety systems testing, staff training etc. as appropriate.	
Priority	Man2	Due Date: 16/03/2021	
Question	W.4	Comment: No up to date records of routine in-house	
Section	Records	fire safety checks were available on-site at the time of inspection.	
Action ID	572689		
Quantity		Recommendation: Management should confirm/ensure	No image available
- Known	N/A	that records of routine fire safety checks are kept in the	
- Potential	N/A	fire safety log book on-site or in a central database.	
Priority	Man2	Due Date: 16/03/2021	
Question	Q.3	Comment: The services riser/cupboards sampled did not	
Section	Limiting Fire Spread	appear to be adequately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors	
Action ID	572675	and by flat 101 do not appear appropriately fire stopped.	
		The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th	
		and 1st-floors. Not all dry-risers were inspected.	
Quantity		Recommendation: The holes noted should be sealed with	
- Known	5	a suitable fire-stopping material such as an intumescent	
- Potential	5	paste. Period of fire resistance required is 60 minutes.	
Priority	В	Due Date: 16/12/2021	
Question	Q.3	Comment: The services riser/cupboards sampled did not	
Section	Limiting Fire Spread	appear to be adequately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors	
Action ID	572690	and by flat 101 do not appear appropriately fire stopped.	
		The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th	
		and 1st-floors. Not all dry-risers were inspected.	
Quantity		Recommendation: The casings noted to the dry-riser	
- Known	4	cupboards should be lined to provide 60 minutes fire	
- Potential	4	resistance.	
Priority	В	Due Date: 16/12/2021 Client Status: Not Complete	



Priority	R	Due Date: Unlimited	Client Status: Not Complete	
Quantity - Known - Potential	42 42	Recommendation: The existing Georgian Wired glass fitted in the fanlights over flat entrance doors, as noted, of this Level 1 Purpose-Built/Stay Put premises should be replaced with EI 30 (30-minutes integrity and insulation) fire resisting glazing (and associated glazing channel and beading).		41
Action ID	572665	entrance doors (except 101 and 102) in this Purpose-Built/ Stay Put premises appears to have 30-minutes integrity only fire resistance. 30-minutes insulation is also required. Fanlight over flat 10 is damaged.		
Section	Flat Entrance/Residents' Bedroom/Bedsit Doors			13
Question	L.4	Comment: The glazing	fitted in fanlights over flat	
Priority	С	Due Date: 16/06/2022	Client Status: Not Complete	
Quantity - Known - Potential	2	Recommendation: Common area fire doors as noted should be fitted with intumescent strips and smoke seals.		
Action ID	572671			
Section	Common Area Fire Doors	adequate intumescent strips and smoke seals except for:- the lift plant room and the service cupboard by flat 101.		
Question	M.6	Comment: Common area fire doors are provided with		
Priority	С	Due Date: 16/06/2022	Client Status: Not Complete	
- Potential	2	perimeter gap between of 3mm.	the door and frame to a maximum	
Quantity - Known	2	Recommendation: The fire doors noted should be repaired (or if necessary replaced) to reduce the		
Action ID	572668			
Section	Common Area Fire Doors	to be in good condition except for:- Excessive gap noted to the service cupboard on the 7th-floor and to the ground floor stair doors (meeting stiles).		
Question	M.2		area fire rated fire doors appear except for: - Excessive gap noted	
Priority	С	Due Date: 16/06/2022	Client Status: Not Complete	
Quantity - Known - Potential	10 10	area should be provided	ke ventilation of 1.5m2 free I to the stair lobbies either Is automatic opening vents tection in the lobbies.	
Action ID	572661	permanent or manually operated ventilation openings for the control of smoke, no ventilation provided to the stair lobby. A PV is provided to the bin chute room and to the head of the stairs. The vent at the head of the stair requires cleaning as the vents are partially blocked with dust/dirt.		
Section	Means of Escape	room has a replacement uPVC fixed shut window. The stairs and the other lobby are provided with adequate		
Question	K.14		nodation lobby with the bin chute	

## 3 Introduction and Scope



#### Limitations of this assessment 3.1

This fire risk assessment report represents the Fire Risk Assessment Company's understanding for the current building designs and use, the fire strategy and proposed evacuation procedures. It is to provide an assessment of the risk to life from fire and does not address building or property protection or business continuity. The report is not an assurance against risk and is based on the best judgement of the consultant involved. The assessment may rely on information given by others and no liability is accepted for the accuracy of such information. Should any of the properties (or their operations) change in any way the risk assessments should be updated accordingly. In addition, it is recommended that this fire risk assessment is reviewed at least annually. Each fire risk assessment identifies areas to which access was not available during the inspection. In certain instances, we may have made recommendations for further inspection in the report, however as general guidance we would recommend that the 'no access' areas are inspected as soon as possible.

### Legislation

This fire risk assessment has been carried out to meet the requirements of The Regulatory Reform (Fire Safety) Order 2005 [the Order]. The following is a summary description of some of the key articles listed in the Order:

Article 3	Defines the responsible person as a.) the employer, bi.) the person in control of the premises, or b.ii) the owner/landlord.
Article 4	Defines the meaning of general fire precautions
Article 5	States 'a person in control of the premises' may be a person who has an obligation for the maintenance / repair of the premises or the safety in the premises.
Article 6	Lists exemptions, which includes domestic premises occupied as a single private dwelling.
Article 8	Requires general fire precautions are undertaken to ensure the safety of employees / relevant persons.
Article 9	Requires the responsible person to carry out a fire risk assessment. This assessment must be reviewed regularly and if there is reason to suspect that it is no longer valid there has been a significant change.
Article 11	Defines the responsible person as a.) the employer, bi.) the person in control of the premises, or b.ii) the owner/landlord.
Article 13	Requires the recording of significant findings from the fire risk assessment, where a.) five or more people are employed, b.) a licence under an enactment is in force, or c.) an alterations notice is in force.
Article 14	Requires that escape routes and exits are kept clear and accessible at all times.
Article 15	Highlights the need for fire drills and competent persons to assist in their undertaking.
Article 17	Requires suitable maintenance of fire safety facilities and equipment.
Article 19	Requires communication with employees, including the significant findings of the fire risk assessment.
Article 20	Requires that any external employers / employees who are working (or have staff working) in premises are provided with relevant information on the risks and the preventive and protective measures in place.
Article 21	Requires that employees are provided with suitable and appropriate training.
Article 22	Requires co-operation / coordination where two or more responsible persons share duties in premises.
Article 23	Lists the general duties of employees at work.



#### 3.3 Risk Level

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following riskbased control plan is based on one advocated by BS 8800 for general health and safety risks:

Risk level	Action and time table
Trivial	No action is required and no detailed records need be kept.
Tolerable	No major additional controls required. However, there might be a need for improvements that involve minor or limited cost
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures
Substantial	Considerable resources might have to be allocated to reduce the risk. If the building is unoccupied, it should not be occupied until the risk has been reduced. If the building is occupied, urgent action should be taken.
Intolerable	Building (or relevant area) should not be occupied until the risk is reduced.

It should be noted that, although the purpose of estimating the risk level is to place the risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly and a reassessment completed by the date recommended in this report.

#### **Recommendation Priorities**

All recommendations made for remedial action as result of the fire risk assessment are assigned a priority in this report. The priorities used have an associated timescale for completion of the recommendations. These are as follows:

Recommendation Priorities:	Recommended Timescales
U	1 day
A	3 months
В	12 months
С	18 months
R	Unlimited
Man1	1 month
Man2	3 months

The above timescales may be altered when the action plan for the premises is collated with other properties in the stock. Please refer to the collated action plan in the Client Portal.

# Property Details



UPRN	123350000A
Number Range	1-43, 101, 102 (no 13)
Building Name	Linacre House
Street Number	
Street	Heathmere Drive
City/Town	Birmingham
Postcode	B37 5EW
Property Designation	General Needs (6 Storeys and over)

Total No. of Floors  Total No. of Floors (common area only)  Total No. of Storeys (ground and above)  Ground Floor Area (m2) (if applicable)  Total Area of All Floors (m2) (if applicable)  Building Layout Description  11 storey purpose-built block of The ground floor entrance hall that gives access to the former	l gives access to a lobby
Total No. of Storeys (ground and above)  Ground Floor Area (m2) (if applicable)  N/A  Total Area of All Floors (m2) (if applicable)  N/A  Building Layout Description  11 storey purpose-built block of The ground floor entrance half	l gives access to a lobby
Ground Floor Area (m2) (if applicable)  N/A  Total Area of All Floors (m2) (if applicable)  N/A  Building Layout Description  11 storey purpose-built block of The ground floor entrance hall	l gives access to a lobby
Total Area of All Floors (m2) (if applicable)  Building Layout Description  11 storey purpose-built block of The ground floor entrance hall	l gives access to a lobby
Building Layout Description 11 storey purpose-built block of The ground floor entrance half	l gives access to a lobby
The ground floor entrance half	l gives access to a lobby
flats, service cupboard and lift access to the communal stairv rear accommodation lobby. The lobby gives access to 2 x flats, alternative access. The upper flobby accessed from the stairved 2 accommodation lobbies. On gives access to 2 flats and the cupboard and the other accommodation lobbies access to 2 flats and the cupboard and the other accommodation lobbies. On gives access to 2 flats and the cupboard and the other accommodation lobbies. On the lift plant room and access chute bin store and electrical in externally adjacent to the rear provided and a sprinkler to the ground floor flats 101 & 102 applications for the storage area.	lobby. The lift lobby gives way, passenger lifts and the ne rear accommodation service cupboard and rear floors are similar with a lift way that gives access to e accommodation lobby bin chute room & dry-riser modation lobby gives access rd. The 10th-floor (level 11) r stair landing with access to door to the roof area. A bin ntake cupboard are accessed alternative exit door. Dry-riser to bin chute bin store only. The
Extent of Common Areas (area assessed)  Entrance hall, stairway, accom lobbies, service cupboards, parbin store, former reception, pla	ssenger lifts, bin chute rooms,
Areas of the building to which access was not available. Service cupboards apart from	the sample inspected.
Total number of Flats/Bedsits/Bedrooms (as applicable) 44	
Number accessed off the Common Area 44	
Flats/Bedsits/Bedrooms sample inspected No residents flats were inspect	ted as agreed with SCH.
Building Use Single Use	
Details of ancillary use (if applicable)	
Total No. of Common Entrances/Exits 2	
Block Accessibility Level	



Building Layout Information	
Total No. of Common Staircases	1

Construction Information	
Construction Type	Concrete Frame
Property Type	Purpose Built
Date of Construction or Conversion (year approx.)	1960
Floor Construction Type	Concrete
Stair Construction Type	Concrete
External Wall Construction Type	External Wall Insulation
External Wall Finish Type	Render
Other Construction Information	The former residents shed storage area appears to have been converted to flats $101~\%~102$ . The original exit from the bottom of the stair into the front lobby with access to the entrance hall has been removed, leaving an exit into the lift lobby with a choice of exits to the front or rear accommodation lobby (front accommodation lobby leads to the entrance hall with exit).

Occupant Information		
Management Extent	Partially Managed Building (Manager or Senior Staff not onsite regularly)	
Details of any onsite management	Management/staff attend the property occasionally during office hours Monday - Friday. 24/7 remote concierge service provided with CCTV coverage.	
Person managing fire safety in the premises	Mark Pinnell - Head of Asset Management	
Person consulted during the FRA	No one. No management was on-site. Telephone contact - Joe Coyle Contracts Officer - was provided & master keys provided	
Number of Residents	Assumed to be two residents per flat	
-Comments	Exact numbers not known	
Number of Employees	No staff on site	
-Comments	Occasional staff attendance expected - low numbers anticipated	
Number of members of the public (maximum estimated)	Residential - low number	
-Comments	Residential block - low number of visitors expected at any one time	
Identified people especially at risk	General Needs - No information	
-Comments	No information, however, General Needs premises so occupants are typical of the general population	

Other information	
Fire loss experience (since last FRA)	None reported, no evidence noted.



Other information	
Any other relevant information	None

In preparing this report reference has been made to a number of key legislative and guidance documents as identified below. Other guidance documents may also be applicable to the assessment which have not been listed here. A full list of guidance documents used in the assessment is available from the risk assessment company on request.

Fire Safety Legislation	
Main fire safety legislation applying to these premises	01) Regulatory Reform (Fire Safety) Order 2005
Other applicable legislation	02) Housing Act 2004

Fire Safety Guidance	
Main fire safety guidance used in this assessment	01) LGA - 'Fire safety in purpose-built blocks of flats' - 2012
Other key fire safety guidance referred to	PAS79 - 'Fire Risk Assessment - a recommended methodology' - 2012



## 5 FRA Questionnaire

#### Elimination or Reduction of Fire Hazards

#### A. Electrical Ignition Sources

Question - A.1: Was access gained to the electrical intake/meter cupboard(s) for the block?

Yes

Comment: The electrical intake room for the premises was accessed at the time of inspection.

Question - A.2: Is the common area fixed electrical installation inspected and tested within the last five years? (State the date of the last test if available)

Comment: The fixed electrical installation appears to have been tested within the last five years according to the test sticker attached. Date of last test: - 2019

Question - A.3: Is the common area fixed electrical installation free from visible defects? (from cursory visual inspection only)

Yes

Comment: No defects were noted in the common area fixed electrical installation (from cursory visual inspection only).

Question - A.4: Is portable appliance testing (PAT) being completed within the common areas?

Comment: Management advises that all portable electrical appliances in common areas are inspected and tested annually as part of a rolling programme.

Question - A.5: Is there a policy in place regarding use of personal electrical appliances within the common areas which is being adhered to at the time of inspection?

Comment: Whilst it was not confirmed that a policy is in place regarding the use of personal portable electrical appliances within the common areas none were seen during the inspection, so this is presumed to be the case.

Question - A.6: If occurring, is the use of multi-way plug adaptors and/or extension leads within the Not Applicable common areas considered acceptable?

Comment: No multi-way adaptors or extension leads were noted in use in the common areas during this inspection.

#### **B. Smoking Policies**

Question - B.1: Are there suitable arrangements in place for those who wish to smoke? (State what arrangements are in place)

Comment: Residents who wish to smoke can do so within their private accommodation only.

Question - B.2: Is there a policy in place to prevent or restrict smoking within the building?

Yes

Comment: Smoking is not permitted in the communal area in accordance with the Smoke-free (Premises and Enforcement) Regulations 2006 and residents are permitted to smoke within their private accommodation only.



Question - B.3: Does the policy in relation to smoking appear to be observed?

Comment: No evidence of illicit smoking was seen in the common area at the time of inspection.

Question - B.4: Is there adequate provision of at least one legible 'No Smoking' sign covering the common area?

Yes

Comment: Adequate 'No Smoking' signage is provided in the common area as required by the Smoke-free (Premises and Enforcement) Regulations 2006.

#### C. Arson

Question - C.1: Are the premises secured against arson by outsiders? (Please state how)

Yes

Comment: The entrance door to the premises is self-closing and is fitted with an intercom and door release system and was locked at the time of inspection. There is a concierge button on the door entry system which connects to a remote concierge service who can give access and oversee the premises via CCTV located externally and throughout the premises.

Question - C.2: Are bins stored in a suitable location? (Please state bin type and location)

Comment: Paladin/Wheelie bins were stored in an integral bin storage room located adjacent to the rear entrance/egress door and accessed externally.

Question - C.3: Are bins adequately secured at or within their storage location? (Please state how bins are secured)

Yes

Comment: The bin storage area/room was locked at the time of inspection.

Question - C.4: Is fire load close to the premises minimised?

Yes

Comment: There was no unnecessary fire load noted close to the building at the time of inspection.

#### D. Space Heating

Question - D.1: Are the common areas of the building provided with any form of fixed space heating system? (State type provided)

No

Comment: The common area has no form of fixed heating and individual residential units have their own heating systems. A district heating system is provided for the flats.

Question - D.3: Are the common areas of the building provided with any form of portable space heating system? (State type provided)

No

Comment: No portable heaters were noted within the common area at the time of inspection.



	$\sim$				
-	Co	$\sim$	VΙ	n	$\alpha$
	$\sim$	$\mathbf{\circ}$	IΝ		ч

Question - E.1: Are common cooking facilities provided in the block?	No
Comment: No common cooking facilities are provided in the premises.	

### F. Lightning

Question - F.1: Do	es the building have a lightning protection system installed?	Yes
Comment: A lightr	ing protection system is provided.	

Question - F.3: From visual inspection, does the lightning protection system appear to be in good condition?	Yes
	and the second second

Comment: The visible parts of the lightning protection system appear to be intact and in good condition from visual inspection.

### G. House-Keeping

Question - G.1: Is the property regularly cleaned to prevent the build up of combustibles?	Yes
Comment: Contact cleaning staff undertake cleaning duties	

Question - G.2: Are combustible items kept clear from sources of ignition such as electrical	Yes
equipment?	

Comment: The electrical intake room was clear of combustible storage at the time of inspection.

	Question - G.3: Are escape routes kept clear of combustible items or waste materials?	Yes
Comment: The common escape routes were clear of combustible materials and waste at the time of inspection.		finspection.

Question - G.4: Are escape routes kept clear of any trip hazards?	Yes
Comment: The common escape routes were clear of any trip hazards at the time of inspection.	

Question - G.5: Are any hazardous materials noted being stored correctly?	Not Applicable
Comment: No hazardous materials were noted in the common area at the time of inspection.	

Question - G.6: Are all other house-keeping issues satisfactory?	Yes
Comment: There were no other house-keeping issues noted at the time of inspection.	



#### H. Contractors

Question - H.1: Are fire safety conditions imposed on outside contractors when working on the premises?

Yes

Comment: Information was received confirming that fire safety conditions are imposed on outside contractors when working on the premises.

Question - H.2: Are there satisfactory controls in place over works carried out on the premises by outside contractors? (e.g. Hot Work Permits)

Comment: Information was received confirming that there are satisfactory controls in place over works carried out on the premises by outside contractors.

Question - H.3: Are there satisfactory controls in place over works carried out in the premises by inhouse staff? (e.g. Hot Work Permits)

Comment: Information was received confirming that there are satisfactory controls in place over works carried out on the premises by inhouse staff.

#### I. Dangerous Substances

Question - I.1: Are any 'dangerous substances' stored or in use within the property?

No

Comment: No dangerous substances were noted being stored or in use at the time of inspection.

#### J. Other Significant Hazards

Question - J.1: Are all other Fire Hazard issues considered satisfactory? [1]

Yes

Comment: There were no other fire hazard issues noted at the time of inspection.



#### General Fire Protection Measures

#### K. Means of Escape

Question - K.1: Is the escape route design deemed satisfactory? (Consider current design codes)

Comment: The means of escape design does not meet current regulations but as the regulations are not retrospective this is deemed satisfactory. Current regulations would require blocks of flats over 30m to have sprinklers installed in residents flats to BS 9251 standard. Also, the communal stairway discharges at ground floor into the lift lobby with access to either the front accommodation lobby with access to the entrance hall with a final exit or the rear accommodation lobby with a final exit. The stair should discharge directly to the outside or to a protected corridor to a final exit. As there is a choice of direction through either the front or rear accommodation lobby this is deemed satisfactory as building regulations are not retrospective.

Question - K.2: Are the escape routes adequately protected? (Consider lobby protection to staircase, if needed)

Yes

Comment: The escape stairs are provided with adequate lobby protection.

Question - K.3: Is there adequate provision of exits for the numbers who may be present?

Yes

Comment: The provision of exits is considered adequate for the number of people expected to be present.

Question - K.4: Is there adequate exit width for the numbers who may be present?

Yes

Comment: The exit widths provided appear adequate for the numbers expected to be present.

Question - K.5: Are doors on escape routes easily opened (and are sliding or revolving doors avoided)?

Yes

Comment: All doors on escape routes are fitted with ironmongery which is easily opened without the use of a key, and there are no sliding or revolving doors.

Question - K.6: Are doors or gates on escape routes provided with electrically operated access control systems? (Describe provision)

Yes

Comment: Doors or gates on escape routes are provided with electrically operated access control systems.



Question - K.7: Are electrically operated access control systems fitted to doors or gates on escape routes provided with override facilities and/or designed to 'fail-safe' on power failure?

Not Known

Comment: It could not be ascertained whether the electrical access control systems fitted to escape route doors/gates are provided with override facilities and/or are designed to 'fail safe' on power failure.

Recommendation: Management should confirm that the secure door entry system continues to operate in the event of a power failure, or fails safe to open. If not, an emergency override facility will be required.



Priority: Man2

Known Quantity: 0

Potential Quantity: 2

Action ID: 572660

Question - K.8: Do final exits open in the direction of escape where necessary?

Comment: Doors on escape routes open in the direction of escape.

Question - K.9: Are travel distances satisfactory? (consider single direction and more than one direction)

Yes

Comment: Travel distances appear to be in line with that allowed in current guidance.

Question - K.10: Are the precautions for all inner rooms suitable?

Not Applicable

Comment: No inner rooms were identified at the time of inspection.

Question - K.11: Are escape routes adequately separated from each other, with fire resisting construction where required?

Yes

Comment: Corridors are provided with smoke control doors where required.

Question - K.12: Are corridors sub-divided with a cross-corridor fire resisting door where required?

Not Applicable

Comment: No corridors requiring cross-corridor fire doors were noted in the property.

Question - K.13: Do escape routes lead to a place of safety?

Comment: Escape routes lead to a place of safety.



Question - K.14: Are the stairs and/or lobbies provided with adequate permanent or manually operated ventilation openings for control of smoke? (State provision)

Comment: The accommodation lobby with the bin chute room has a replacement uPVC fixed shut window. The stairs and the other lobby are provided with adequate permanent or manually operated ventilation openings for the control of smoke, no ventilation provided to the stair lobby. A PV is provided to the bin chute room and to the head of the stairs. The vent at the head of the stair requires cleaning as the vents are partially blocked with dust/dirt.

Recommendation: Smoke ventilation of 1.5m2 free area should be provided to the stair lobbies either as permanent vents or as automatic opening vents controlled by smoke detection in the lobbies.



Priority: C

Known Quantity: 10

Potential Quantity: 10

Action ID: 572661

Recommendation: The smoke vent noted to the head of the stairs should be cleaned.



Priority: Man2

Known Quantity: 1

Potential Quantity: 1

Action ID: 572662

Question - K.15: Are the stairs and/or lobbies provided with an adequate automatic or remotely operated smoke ventilation system? (State provision)

Not Applicable

Comment: Current guidelines require that automatic opening vents (AOV) in the lobbies, where the fire is initiated, and the vent at the head of the stair should be activated simultaneously by automatic smoke detectors in the common area. Automatic ventilation is not provided, but as building regulations are not retrospective this is deemed satisfactory, also see K14.

Question - K.16: Are there suitable arrangements in the building for means of escape for people with disabilities?

Not Known

Comment: There was no information available regarding arrangements in the building for means of escape for people with disabilities.

Recommendation: Management should encourage residents of this General Needs property to contact the building manager if they require assistance in developing a personal emergency evacuation plan (PEEP) or other fire safety advice. This could be achieved by adding a contact reference for assistance to the fire action notices for the premises, by providing additional separate notices containing the information or making direct contact with residents via letter, flyer or website for example.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572663

Question - K.17: Are all other means of escape issues satisfactory? [1]

Yes

Comment: There were no other means of escape issues noted at the time of inspection.



Question - K.19: What is the current evacuation strategy for the property?

Stay Put

Comment: The current evacuation strategy is Stay Put as denoted by the fire action notices displayed in the common area.

Question - K.20: Is the current evacuation strategy for the property considered appropriate?

Yes

Comment: The premises is purpose-built with an adequate standard of compartmentation. The current Stay Put evacuation strategy is considered appropriate.

Question - K.21: What is the recommended evacuation strategy for the property?

Stay Put

Comment:

#### L. Flat Entrance/Residents' Bedroom/Bedsit Doors

Question - L.1: Are all flat entrance (or residents' bedroom/bedsit) doors and frames appropriately fire rated? (State type and standard of doors)

Yes

Comment: Flat entrance doors/frames are original 'notional' timber fire doors (N.B. - From limited visual inspection; certification not seen; adequacy of installation not confirmed).

Question - L.2: Are fire rated flat entrance (or residents' bedroom/bedsit) doors and frames in good condition - not in need of repair?

Comment: Fire-rated flat entrance doors and frames appear to be in good condition except for:- Flat entrance doors 4 & 12 appear damaged.

Recommendation: Doors and frames as noted should be replaced with FD30S self-closing fire door sets, installed strictly in accordance with the manufacturer's test certification.



Priority: A

Known Quantity: 2

Potential Quantity: 2

Action ID: 572664

Question - L.3: Is all glazing to flat entrance (or residents' bedroom/bedsit) doors appropriately fire rated?

Not Applicable

Comment: There is no glazing present to any flat entrance doors in this property.



Question - L.4: Are fanlights above flat entrance (or residents' bedroom/bedsit) doors appropriately fire rated?

Comment: The glazing fitted in fanlights over flat entrance doors (except 101 and 102) in this Purpose-Built/Stay Put premises appears to have 30-minutes integrity only fire resistance. 30-minutes insulation is also required. Fanlight over flat 10 is damaged.

Recommendation: The existing Georgian Wired glass fitted in the fanlights over flat entrance doors, as noted, of this Level 1 Purpose-Built/Stay Put premises should be replaced with EI 30 (30-minutes integrity and insulation) fire resisting glazing (and associated glazing channel and beading).



Priority: R

Known Quantity: 42

Potential Quantity: 42

Action ID: 572665

Question - L.5: Are side panels to flat entrance (or residents' bedroom/bedsit) doors appropriately fire rated?

Not Applicable

Comment: There are no side panels to the flat entrance doors in this property.

Question - L.6: Are all sampled flat entrance (or residents' bedroom/bedsit) doors fitted with adequate self-closing devices and is there a rolling programme of fire door checks in place to include those not sampled?

**Not Known** 

Comment: No access was possible to any of the flat entrance doors to confirm that they are fitted with adequate self-closing devices.

Recommendation: Management should establish an ongoing rolling programme of checks to all flat entrance doors to confirm that self-closers are fitted and remain effective.

No image available

Priority: Man2

Known Quantity: 0

Potential Quantity: 44

Action ID: 572666

Question - L.7: Are all sampled flat entrance (or residents' bedroom/bedsit) doors fitted with intumescent strips and cold smoke seals and is there a rolling programme of fire door checks in place to include those not sampled?

Not Known

Comment: There was no access possible to any of the flat entrance doors to confirm that they are fitted with intumescent strips and cold smoke seals.

Recommendation: Management should establish an ongoing rolling programme of checks to all flat entrance doors to confirm that strips and seals are fitted and remain effective.

No image available

Priority: Man2

Known Quantity: 0

Potential Quantity: 44

Action ID: 572667

Question - L.8: Are letterboxes to flat entrance (or residents' bedroom/bedsit) doors satisfactory? (State only if missing, damaged or uPVC)

Yes

Comment: Letterboxes fitted to flat entrance doors have metal flaps and appear to be in good condition.



Question - L.9: Are all other flat entrance (or residents' bedroom/bedsit) door issues satisfactory? [1]

Comment: There were no other flat entrance door issues noted at the time of inspection.

#### M. Common Area Fire Doors

Question - M.1: Are all common area doors and frames requiring fire resistance appropriately fire rated?

Comment: All common area fire doors and/or frames appear to be appropriately fire rated. FD30 and FD60 timber and glazed fire doors(N.B. -From limited visual inspection; certification not seen; adequacy of installation not confirmed).

Question - M.2: Are all common area fire rated fire door sets in good condition - and not in need of repair?

Comment: All common area fire rated fire doors appear to be in good condition except for:- Excessive gap noted to the service cupboard on the 7th-floor and to the ground floor stair doors (meeting stiles).

Recommendation: The fire doors noted should be repaired (or if necessary replaced) to reduce the perimeter gap between the door and frame to a maximum of 3mm.



Priority: C

Known Quantity: 2

Potential Quantity: 2

Action ID: 572668

#### Question - M.3: Is all glazing to common area fire doors appropriately fire rated?

Yes

Comment: All glazing to common area fire doors appears to be the original Georgian wired fire-rated. Current regulation would require glazing to the stairway and accommodation lobby doors to be 60-minute integrity and insulation below 1100mm - side panels or 100mm doors.

Question - M.4: Are fanlights/side panels to common area fire doors appropriately fire rated?

No

Comment: Fanlights/side panels to common area fire doors appear to be the original Georgian-wired fire rated. Current regulation would require glazing to the stairway and accommodation lobby door side panels to be 60-minute integrity and insulation below 1100mm. The side panel on the 1st-floor to flats 4 & 5 is damaged.

Recommendation: 60-minute fire-resisting integrity and insulation glazing/material should be installed in the side panels to common area fire doors as noted (side panel on the 1st-floor to flats 4 & 5).



Priority: A

Known Quantity: 1

Potential Quantity: 1

Action ID: 572669



Question - M.5: Are common area fire door sets fitted with adequate self-closing devices where required?

Comment: Not all common area fire doors are fitted with adequate self-closing devices where required -The following doors are not fully closing into the frames with the aid of the self-closing device, doors to the accommodation lobbies to flats 40 & 43 and 28 & 31.

Recommendation: The self-closing device should be repaired or an effective self-closing device should be fitted to the doors as noted.



Priority: A

Known Quantity: 2

Potential Quantity: 2

Action ID: 572670

Question - M.6: Are intumescent strips and smoke seals provided to common area fire doors?

Comment: Common area fire doors are provided with adequate intumescent strips and smoke seals except for:- the lift plant room and the service cupboard by flat 101.

Recommendation: Common area fire doors as noted should be fitted with intumescent strips and smoke seals.



Priority: C

Known Quantity: 2

Potential Quantity: 2

Action ID: 572671

Question - M.7: Are common area fire door sets adequate otherwise? (Ironmongery, hold open hooks etc.)

Yes

Comment: Common area fire doors are considered adequate (subject to any issues noted elsewhere in this report).

Question - M.8: Are all other common area fire door issues satisfactory?

Yes

Comment: No other common area fire door issues noted at the time of inspection.

#### N. Emergency Lighting

Question - N.1: Is emergency lighting provided to the common areas of the block? (if 'Yes' then describe provision)

Yes

Comment: Emergency lighting is provided to the common areas of the premises.



Question - N.2: From visual inspection, does the emergency lighting system appear to be in good working order?

Comment: The emergency lighting provided appears to be in good working order from visual inspection (system not tested at time of inspection).

Question - N.3: From visual inspection, does the coverage of the emergency lighting system provided appear to be adequate? (Internal and external)

Yes

Comment: The coverage of the emergency lighting provided appears to be adequate.

#### O. Fire Safety Signs and Notices

Question - O.1: Is there adequate provision of fire action notices within the common areas? (Consider recommended evacuation strategy; unsuitability of generic notices and location/visibility of any notices provided)

Yes

Comment: A suitable Fire Action Notice indicating the recommended Stay Put evacuation strategy was displayed within the common area.

Question - O.2: Is fire door signage adequate? (Consider 'Fire door keep shut', 'Fire door keep locked shut' and 'Automatic Fire Door Keep Clear' signage. Exclude doors recommended for replacement)

Yes

Comment: Fire door signage is considered adequate.

Question - O.3: If required, is directional/exit signage adequate?

Yes

Comment: Directional and exit signage is considered adequate.

Question - O.4: Are all other fire safety signs issues satisfactory? [1] (Consider lift signage, and escape door signs. 'No Smoking' signage is covered in the Smoking Policies section.)

Yes

Comment: No other fire safety signs issues were noted at the time of inspection.

#### P. Means of Giving Warning in Case of Fire

Question - P.1: Has the building got a BS5839 electrical fire detection and alarm (or detection only) system comprising manual call points and/or automatic detection? (Provide details)

Comment: There is an L5 automatic fire detection/alarm system installed within the bin chute bin store, service cupboard by fat 101 and electrical intake room comprising of a fire alarm panel, smoke detectors and sounders.

Question - P.2: From visual inspection, does the common area fire detection/alarm system appear to be in good working condition?

Comment: The common area fire detection/alarm system appears to be in good working order (from visual inspection only - no system tests were carried out).



Question - P.3: Is the Grade and Category of the common area fire detection/alarm system appropriate for the building type, occupancy and fire risk?

Comment: The L5 system installed is appropriate for early warning in the ancillary rooms in which it is installed.

Question - P.5: If applicable, are independent domestic hard-wired smoke/heat alarm systems within the sampled flats installed to a suitable standard and is there a rolling programme of checks in place to include those not sampled? (Grade D LD3 minimum standard)

Not Known

Comment: No access was possible to any of the flats to confirm that they are fitted with an adequate smoke alarm system.

Recommendation: All flats should be checked to confirm provision and working condition of at least Grade D LD3 smoke alarm systems to BS 5839-6:2019. An ongoing rolling programme of checks should be confirmed to be in place. If new systems are required to be installed these should be to Grade D1 LD2 standard.

No image available

Priority: Man2

Known Quantity: 0

Potential Quantity: 44

Action ID: 572672

Question - P.6: Is remote monitoring of fire alarm signals required, via social alarms linked to smoke Not Applicable alarm systems within individual flats (e.g. in Sheltered Housing), and/or a connection from the common fire alarm system (if provided) to an Alarm Receiving Centre?

Comment: Remote fire alarm system monitoring is not a requirement for this property type and occupancy. The 24/7 concierge service is linked to the fire alarm system and door entry system.

Question - P.9: Are all other fire detection and alarm system issues satisfactory? [1]

Yes

Comment: There were no other fire detection/alarm system issues noted at the time of inspection.

#### Q. Limiting Fire Spread

Question - Q.1: In general, is the level of compartmentation adequate for the use and evacuation strategy for the property? (Special consideration should be given to converted or non 'purpose built' premises)

Yes

Comment: The premises are purpose-built with what appears to be an adequate standard of compartmentation (subject to recommendations which may be noted elsewhere in this report).



Question - Q.2: Are any hidden voids identified during the inspection appropriately enclosed and/ or fire-stopped? (consider above suspended ceilings and behind casings)

Not Known

Comment: It was not possible to sample inspect the hidden voids identified without causing damage or requiring opening up. There appear to be flush floor to ceiling riser in the bin chute rooms and sealed false ceilings throughout the common areas. There are also boxed-in services ducts within the stairway, lift lobbies and floor to ceiling service risers in the accommodation lobbies (x 3) that are screwed shut of unknown construction. It is not possible to check compartmentation behind without an intrusive inspection. No access was available to check the fire rating of the walls between the bin-chute rooms and accommodation lobbies.

Recommendation: Management should undertake an intrusive inspection of the hidden voids noted to confirm/ensure that compartmentation within is adequate.



Priority: Man2

Known Quantity: 0

compromised at services penetrations etc.

Potential Quantity: 1

Action ID: 572673



Priority: Man2

Known Quantity: 0

Potential Quantity: 1

Action ID: 572674

Recommendation: Management should undertake intrusive checks to ensure/confirm the walls between the bin chute rooms and accommodation lobby is appropriately fire rated (120-minute standard - current regulations)

Recommendation: A sample check should be made of the boxed-in services ductwork to confirm that the construction is adequately fire resisting and that compartmentation behind has not been

Priority: Man2

Known Quantity: 0

Potential Quantity: 10

Action ID: 572691

No image available



Question - Q.3: Are services risers, shafts, ducts and cupboards in the common area appropriately enclosed with fire resisting construction and adequately fire-stopped?

Comment: The services riser/cupboards sampled did not appear to be adequately fire-stopped. Sample inspected service cupboards on the 10th, 7th, 4th and 1st-floors and by flat 101 do not appear appropriately fire stopped. The dry-riser cupboards that also contain services are not lined to the inside of the cupboards on the 10th, 7th, 5th and 1st-floors. Not all dry-risers were inspected.

Recommendation: The holes noted should be sealed with a suitable fire-stopping material such as an intumescent paste. Period of fire resistance required is 60 minutes.



Priority: B

Known Quantity: 5

Potential Quantity: 5

Action ID: 572675

Recommendation: Management should check within services risers cupboards not inspected to confirm that they are adequately fire-stopped.



Priority: Man2

Known Quantity: 0

Potential Quantity: 11

Action ID: 572676

Recommendation: The casings noted to the dry-riser cupboards should be lined to provide 60 minutes fire resistance.



Priority: B

Known Quantity: 4

Potential Quantity: 4

Action ID: 572690

Question - Q.4: Are pipes and other services provided with adequate fire-stopping measures as required where they pass through fire resisting construction? (Consider fire collars etc)

Comment: Firestopping around services exiting the risers/cupboards sampled would appear to be adequate.

Question - Q.5: If a waste chute is provided within the building are adequate measures in place to limit fire spread/growth? (Consider provision of fusible link dampers and sprinklers etc)

Yes

Comment: A waste chute is provided in the building, which is located in a ventilated room. Hopper doors ARE self-closing and HAVE adequate seals. A fusible link damper IS fitted to the base of the waste chute. A sprinkler IS provided at the base of the waste chute, also see K2.



Not Applicable Question - Q.6: Are any roof space voids present above the common areas provided with adequate compartmentation to support the evacuation strategy for the building? Comment: There were no roof voids noted above the common areas - the building has a flat roof. Question - Q.7: Are electrical installations/intakes enclosed in fire rated construction? (Where Yes necessary) Comment: The electrical intake/meter cupboard appears to be adequately fire resisting and firestopped. Question - Q.8: Is compartmentation maintained behind electrical meter cabinets recessed into flat Not Applicable walls and/or between the meter cabinet and the common area? Comment: There are no electrical meter cabinets recessed into flat compartment walls in this property. Question - Q.9: If present, are common ventilation systems, ventilation ducts and grills adequate to Not Applicable limit fire spread/growth? (Consider dampers etc.) Comment: There were no common ventilation systems noted within this property. Question - Q.10: Are wall and ceiling linings appropriate to limit fire spread? Yes Comment: The wall and ceiling linings would appear to be appropriate to limit fire spread. Question - Q.11: If provided, are soft furnishings in common areas appropriate to limit fire spread/ Not Applicable growth? Comment: Not applicable to these premises at the time of this assessment.

Question - Q.12: If provided, are curtains or drapes within common areas appropriate to limit fire

Comment: Not applicable to these premises at the time of this assessment.

spread/growth?

Not Applicable



Question - Q.13: Are the external walls of the building satisfactory with regard to fire spread? (Consider combustibility of cladding, external insulation systems, spandrel panels and balconies etc. if provided).

**Not Known** 

Comment: No information was available on site to confirm if the external wall insulation system met the requirements of the Building Regulations with regards to limited combustibility and surface fire spread requirements. Advised by management that the wall insulation is mineral wool insulation fixed directly to the wall of the block with a render finish, no information was available to confirm this.

Recommendation: Management should confirm that the external wall insulation system meets Building Regulations requirements with regards to limited combustibility and surface fire spread properties.



Priority: Man1

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572677

Question - Q.14: Are all other fire spread/compartmentation issues satisfactory? [1]

Comment: There were no other fire spread/compartmentation issues noted at the time of inspection.

#### R. Fire Extinguishing Appliances

Question - R.1: Are portable fire extinguishers provided in the common areas, including staff/plant rooms? (Give details of any provision)

Yes

Comment: Extinguishers were provided as follows:- C02 extinguishers provided in the electrical intake room and lift plant room.

Question - R.2: Is it considered appropriate to provide portable fire extinguishers in the areas noted Yes given the building occupancy?

Comment: The provision of portable fire extinguishers is considered appropriate for this property as they are in non-residential areas only where staff/contractors are expected to be trained in their safe usage.

Question - R.3: Is the existing provision of portable fire extinguishers considered adequate for the building (type, number, location etc.)?

Comment: The type, number and location of portable fire extinguishers are considered adequate for the risks present.

Question - R.4: Are all fire extinguishing appliances suitably located and readily accessible?

Yes

Comment: The portable fire extinguishers provided are appropriately located and readily accessible.



#### S. Other Fire Safety Systems and Equipment

Question - S.1: Is the building provided with drop key override switch facilities for Fire and Rescue Service access?

Comment: A drop key override switch facility is provided which worked satisfactorily when tested.

Question - S.2: Is the building provided with a fire mains system? (Dry or wet riser etc.)

Comment: The building is provided with a fire main: - Fire main provided with outlets in the accommodation lobbies and an inlet in the rear ground floor entrance lobby.

Question - S.3: Is the building provided with a lift (or lifts) used for fire safety purposes? (Firefighting, fireman's or evacuation lift)

Yes

Comment: The building is provided with a lift used for fire safety purposes:- a fireman's override switch provided on the ground floor level.

Question - S.4: Is the building provided with disabled evacuation aids? (Evacuation chairs, sheets, mats or sledges etc.)

No

Comment: The building has no apparatus for the evacuation of people with disabilities.

Question - S.5: Is a sprinkler system provided within the building? (provide details of type and extent)

Comment: The sprinkler system provided in the building is located in the bin chute bin store only.

Question - S.6: Are hose reels provided within the building?

No

Comment: Hose reels are not provided within the building.

Question - S.7: Is any other relevant fire safety system or equipment installed? [1] (state type of system and comment as necessary)

No

Comment: There are no other relevant fire safety systems or equipment installed.



#### Fire Safety Management

#### T. Procedures and Arrangements

Question - T.1: Please CONFIRM the Property Designation

A designation other than General Needs (5 Storeys and under)

Comment: 11 storey general needs block

Question - T.2: Has a competent person(s) been appointed within the organisation to assist in undertaking preventative and protective fire safety measures?

Comment: Management advises that a competent person has been appointed within the organisation to assist with undertaking preventative and protective fire safety measures. Savills is engaged to provide risk assessment and other fire safety advice.

Question - T.3: Is there a suitable record of the fire safety arrangements?

Not Known

Comment: No suitable record of the fire safety arrangements for the building was available for inspection during the inspection.

Recommendation: Management should confirm/ensure that a suitable documentary record of the fire safety arrangements for the building is held within the building or at a central location. This should cover all arrangements for the effective planning, organisation, control, monitoring and review of the preventative and protective measures in place and should include a plan for responding in the immediate aftermath of a fire incident.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572678

Question - T.4: Are there appropriate procedures in place in the event of fire and are these documented?

Yes

Comment: Documented fire safety procedures for residents are displayed in the Fire Action Notices.

Question - T.5: Are there suitable arrangements for calling the Fire Service, meeting them on arrival and providing relevant information?

Comment: The building is not staffed and residents are required to self-evacuate if necessary. Residents will call the Fire and Rescue Service if they become aware of a fire. Concierge service has remote 24/7 coverage of the property vis CCTV.

Question - T.6: Are there suitable fire assembly points away from any risk?

Not Applicable

Comment: The building has a Stay Put evacuation strategy and no general assembly points are required.

Question - T.7: Are there adequate procedures in place for the evacuation of people with a disability who are likely to be present?

Not Applicable

Comment: The building has a Stay Put evacuation strategy, with no full-time staff presence. Residents are expected to self-evacuate if necessary. (Refer to Question K.16).



Not Applicable Question - T.8: Are staff nominated to use fire extinguishing appliances in the event of fire? Comment: There is no staff presence in the building except for occasional attendance. Question - T.9: Are staff nominated to assist with evacuations in the event of fire? Not Applicable Comment: There is no staff presence in the building except for occasional attendance. **Not Known** Question - T.10: Is there appropriate liaison with the local Fire and Rescue Service? Comment: It is not known if liaison with the local Fire and Rescue Service takes place. Recommendation: Management should confirm/ensure appropriate liaison takes place with the local Fire and Rescue Service and that familiarisation visits are carried out. Records of all No image available engagement should be kept on-site or in a central database. Priority: Man2 Known Quantity: N/A Action ID: 572679 Potential Quantity: N/A Not Known Question - T.11: Are routine in-house fire safety checks carried out? (Including control and indicating equipment normal, extinguishers in place and visible, lighting working, fire doors (frames/seals/closing), fastenings, final exits and escape routes clear) Comment: It is not known if routine fire safety checks are being carried out. Recommendation: Management should confirm/ensure that routine in-house fire safety checks are carried out on a regular basis (daily or weekly depending on building usage) and records kept No image available on-site or in a central database. Priority: Man2 Known Quantity: N/A Action ID: 572680 Potential Quantity: N/A Question - T.12: Are all other fire safety management issues satisfactory? Yes Comment: There were no other fire safety management issues noted at the time of inspection. U. Training and Drills Question - U.1: Do staff receive adequate induction and annual refresher fire safety training (to Not Applicable include fire risks in the premises, fire safety measures in the building, action in the event of fire and on hearing alarm)? Comment: The building has no staff present so fire safety training is not required. Question - U.4: Are fire drills carried out at appropriate intervals? Not Applicable Comment: The building has a Stay Put evacuation strategy so fire drills are not required.



#### V. Testing and Maintenance

Question - V.1: Is the common area fire detection/alarm system tested and serviced in accordance with relevant guidance?

Not Known

Comment: No evidence was available on-site to confirm regular inspection, testing and servicing of the system is being carried out.

Recommendation: Management should confirm/ensure that the Grade A/Part 1 common area fire detection and alarm system is tested weekly and serviced six monthly in accordance with BS 5839-1 and records kept on-site or in a central database.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572681

Question - V.2: Is the common area emergency lighting system tested and serviced in accordance with relevant guidance?

Not Known

Comment: No evidence was available on-site to confirm regular inspection, testing and servicing of the system is being carried out.

Recommendation: Management should confirm/ensure that the common area emergency lighting system is tested monthly and serviced annually in accordance with BS 5266-8:2004 and records kept on-site or in a central database.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572682

Question - V.3: Are all fire extinguishers tested and serviced in accordance with relevant guidance?

Yes

Comment: There was evidence available on-site to confirm that regular inspection, testing and servicing is being carried out.

Question - V.4: Are fire mains inspected, tested and serviced in accordance with relevant guidance?

Comment: There was evidence available on-site to confirm that regular inspection, testing and servicing is being carried out.

Question - V.5: Is the lightning protection system inspected and tested in accordance with relevant quidance?

Not Known

Comment: No evidence was available on-site to confirm regular inspection, testing and servicing of the system is being carried out.

Recommendation: Management should confirm/ensure that the lightning protection system is tested and serviced annually in accordance with BS EN 62305 and records kept on-site or in a central database.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572683

Question - V.8: Are access control systems inspected, tested and serviced in accordance with relevant guidance?

**Not Known** 

Comment: No evidence was available on-site to confirm regular inspection, testing and servicing of the system is being carried out.

Recommendation: Management should confirm/ensure that the access control system is inspected, tested and serviced in accordance with relevant guidance and records kept on-site or in a central database.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572684



Question - V.9: Are drop key override switch facilities for Fire and Rescue Service access working satisfactorily, inspected, tested and serviced in accordance with relevant guidance?

**Not Known** 

Comment: No evidence was available on-site to confirm regular inspection, testing and servicing of the system is being carried out.

Recommendation: Management should confirm/ensure that the drop key override switch facilities for Fire and Rescue Service access are inspected, tested and serviced in accordance with relevant guidance and records kept on-site or in a central database.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572685

Question - V.10: Are lifts in the building used for fire safety purposes inspected, tested and serviced in accordance with relevant guidance? (Firefighting, fireman's or evacuation lift)

Comment: No evidence was available on-site to confirm regular inspection, testing and servicing of the system is being carried out.

Recommendation: Management should confirm/ensure that lifts are inspected, tested and serviced in accordance with the relevant legislation and guidance and records kept on-site or in a central database.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572686

Question - V.11: Is the sprinkler system provided within the building inspected, tested and serviced in accordance with relevant guidance?

Not Known

Comment: No evidence was available on-site to confirm regular inspection, testing and servicing of the system is being carried out.

Recommendation: Management should confirm/ensure that the sprinkler system is inspected, tested and serviced in accordance with relevant guidance and records kept on-site or in a central database.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572687

#### W. Records

Question - W.1: Is there a log book on the premises?

No

Comment: No log book was available on site during the inspection.

Recommendation: Management should confirm/ensure that a fire safety log book is provided to enable recording as required of all relevant fire safety events such as fire drills, routine checks, Fire and Rescue Service visits, fire safety systems testing, staff training etc. as appropriate.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572688

Question - W.2: Are details of fire drills recorded?

Not Applicable

Comment: The building has a Stay Put evacuation strategy so fire drills are not required.

Question - W.3: Are details of fire safety training recorded?

Not Applicable

Comment: There are no staff present on-site so fire safety training is not required.



Question - W.4: Are routine in-house fire safety checks recorded?

Not Known

Comment: No up to date records of routine in-house fire safety checks were available on-site at the time of inspection.

Recommendation: Management should confirm/ensure that records of routine fire safety checks

are kept in the fire safety log book on-site or in a central database.

No image available

Priority: Man2

Known Quantity: N/A

Potential Quantity: N/A

Action ID: 572689

Question - W.7: Are records kept of the fire extinguisher inspections, tests and servicing?

Comment: There were records on site of regular inspection, testing and/or servicing of the system installed.

Question - W.8: Are fire mains inspections, tests and services recorded?

Yes

Comment: There were records on site of regular inspection, testing and/or servicing of the system installed.



#### **Additional Issues**

#### X. Electrical Services

Question - X.1: Are any wiring systems visible within the common escape route(s) supported in accordance with BS 7671:2018 (as amended) such that they will not be liable to premature collapse in the event of fire? (Consider the use of non-metallic cable clips, ties etc.)

Not Applicable

Comment: There were no surface mounted wiring systems noted within the common escape routes.

#### Y. Gas Services

Question - Y.1: Are there any fixed gas installations present within the common parts of the building? (Consider gas pipework and meters)

No

Comment: There were no gas installations noted within the common parts of the building.

#### Z. Other Issues

Question - Z.1: Are all other issues deemed satisfactory? [1]	Yes
Comment: There were no other relevant issues noted at the time of inspection.	

## **BAFE Certificate**



Part 1a	Name & Address of Certificated Organisation: Savills (UK) Ltd, 33 Margaret Street, London, W1G 0JD
Part 1b	BAFE registration number of issuing Certificated Organization: NSI00539
Part 2	Name of client: Solihull Community Housing
Part 3a	Address of premises for which the fire risk assessment was carried out: 1-43, 101, 102 (no 13) Linacre House Heathmere Drive Birmingham B37 5EW
Part 3b	Part or parts of the premises to which the fire risk assessment applies:  Common Parts only (not dwellings, where applicable)
Part 4	Brief description of the scope and purpose of the fire risk assessment: Life Safety (as per agreed Specification)
Part 5	Effective date of the fire risk assessment: 16/12/2020
Part 6	Recommended date for reassessment of the premises: 16/12/2021
Part 7	Unique reference number of this certificate: Refer to Master Property List

This certificate is issued by the organization named in Part 1 of the schedule in respect of fire risk assessment provided for the person(s) or organization named in Part 2 of the schedule at the premises and / or part of the premises identified in Part 3 of the schedule.

We, being currently a 'Certificated Organization' in respect of fire risk assessment identified in the schedule, certify that the fire risk assessment referred to in the schedule complies with the Specification identified in the schedule and with all other requirements as currently laid down within the BAFE SP205 Scheme in respect of such fire risk assessment.

Signed for and on behalf of the issuing Certificated Organization:









Date of Issue

16/12/2020

