Summary of Examinations

Owner: Solihull Metropolitan Borough Council Remedial Items: 2

Site ID: Oriel House Advisory Items:

Site: Oriel House Serviceable Items: 3

Inspected By: Andrew Russell Not Inspected Items: 0



DocumentID: NOTI69411 Our Reference: C42628 Generated: 16 March 2021

Building/Location	Item Description/YoM	User Ref	Manufacturer/Serial No.	SWL	Freq of Exam	Next Insp Date	Comment(s)	Client Ref 1	Priority
Lift Motor Room	Runway ()	17717B	/ 17717B(1)	1000 Kg	12	15/03/2022	S - Serviceable.	L0140	S
Lift Motor Room	Runway ()	17717B	/ 17717B (2)	1000 Kg	12	15/03/2022	S - Serviceable.	L0140	S
Lift Motor Room	Runway ()	17717A	/ 17717A	1000 Kg	12	15/03/2022	S - Serviceable.	L0140	S
Lobby Area (Left Hand) Odd	Electric Passenger/Goods Lift - 10 floors, gearless. ()	EMR 384	Excelsior (refurb 2017) / EMR 384	8 Persons/630 Kg as marked	6	15/09/2021	R30 - The ground floor landing door is binding when opening and closing, also the self close function is is very poor - Remedy R30 - The 7th floor landing call assembly on the wall is unsecure and close to falling off - Re-secure A - It is noted the trap door area is not clearly defined and does not have a Safe Working Load marked - Advise to address A - There is no visible smoke alarm present within the motor room - Advise to address	L0140	R30, R30, A, A
Lobby area (Right hand) Even	Electric Passenger/Goods Lift - 10 floors, gearless ()	EMR 383	Excelsior (Refurb 2017) / EMR 383	8 Persons/630 Kg as marked	6	15/09/2021	A - There is no visible smoke alarm present within the motor room - Advise to address	L0140	- A
Stairs	Lifting Ring ()	LP17717.1	/ LP17717.1	1000 Kg	12	15/03/2022	A - Visual inspection carried out	L0140	A
Stairs	Lifting Ring ()	LP17717.3	/ LP17717.3	1000 Kg	12	15/03/2022	A - Visual inspection carried out	L0140	A
Stairs	Lifting Ring ()	LP17717.4	/ LP17717.4	1000 Kg	12	15/03/2022	A - Visual inspection carried out	L0140	A
Stairs	Lifting Ring ()	LP17717.2	/ LP17717.2	1000 Kg	12	15/03/2022	A - Visual inspection carried out	L0140	A