

# Summary of Examinations

For Insp Dates: 14/05/2021

To: 14/05/2021

Unserviceable Items: 0

Owner: Solihull Metropolitan Borough Council

Remedial Items: 2

Site ID: Wingfield House

Advisory Items: 1

Site: Wingfield House

Serviceable Items: 3

Inspected By: Andrew Russell

Not Inspected Items: 0



DocumentID: NOTI72417

Our Reference: C44580

Generated: 17 May 2021

| Building/Location | Item Description/YoM                                     | User Ref | Manufacturer/Serial No. | SWL                | Freq of Exam | Next Insp Date | Comment(s)  | Client Ref 1 | Priority    |
|-------------------|--|----------|-------------------------|--------------------|--------------|----------------|---|--------------|-------------|
| Lift motor room   | RUNWAY BEAM (→)  | 896/9A   | N/K / 896/9A            | 1500 kg            | 12           | 14/05/2022     | S - Serviceable.  | L0164        | S           |
| Lift motor room   | Lifting eye (→)  | LP01     | / LP01                  | 1 Ton              | 12           | 14/05/2022     | S - Serviceable.  | L0164        | S           |
| Lift motor room   | Lifting eye (→)  | LP02     | / LP02                  | 1 Ton              | 12           | 14/05/2022     | S - Serviceable.  | L0164        | S           |
| Lobby             | Electric Passenger/Goods Lift - 9 floor, gearless (2015) | 96/1574  | LES Refurb / C 15 9508  | 630 kg / 8 Persons | 6            | 14/11/2021     | <b>R30</b> - As per previous inspection - The upper engineers inspection switch has been locked out of alignment with the ramp so it will not operate - Remedy<br><b>R60</b> - As per previous inspection - Trap door as located in motor room does not have a safe working load marked - Confirm and clearly mark.<br><b>A</b> - Suspension ropes and safety gear rope remain serviceable. | L0164        | R30, R60, A |