

Summary of Examinations

For Insp Dates: 05/07/2021

To: 05/07/2021

Owner: Solihull Metropolitan Borough Council

Site ID: Darwin House

Site: Darwin House

Inspected By: Andrew Russell

Unserviceable Items: 0

Remedial Items: 1

Advisory Items: 0

Serviceable Items: 4

Not Inspected Items: 0



Document ID: NOTI72438

Our Reference: C44601

Generated: 07 July 2021

Building/Location	Item Description/YoM	User Ref	Manufacturer/Serial No.	SWL	Freq of Exam	Next Insp Date	Comment(s)	Client Ref 1	Priority
FOYER	ELECTRIC PASSENGER / GOODS LIFT (8 Floors) (2014)	70702 (Even Lift)	LES / 70702	600 kg / 8 Persons	6	05/01/2022	R60 - Concierge cannot hear the conversation on the autodialler system - Investigate and remedy	L0096	R60
FOYER	ELECTRIC PASSENGER / GOODS LIFT (8 Floors) (2014)	70701 (Odd Lift)	LES / 70701	600 kg / 8 Persons	6	05/01/2022	S - Serviceable.	L0096	S
LIFT MOTOR ROOM	RUNWAY BEAM (→)	20813.E	N/K / 20813.E	1000 kg	12	05/07/2022	S - Serviceable.	L0096	S
LIFT MOTOR ROOM	RUNWAY BEAM (→)	20813.F	N/K / 20813.F	1000 kg	12	05/07/2022	S - Serviceable.	L0096	S
LIFT MOTOR ROOM	RUNWAY BEAM (→)	20813.G	N/K / 20813.G	1000 kg	12	05/07/2022	S - Serviceable.	L0096	S