

Summary of Examinations

For Insp Dates: 14/05/2021

To: 14/05/2021

Unserviceable Items: 0

Owner: Solihull Metropolitan Borough Council

Remedial Items: 0

Site ID: Trevelyan House

Advisory Items: 3

Site: Trevelyan House

Serviceable Items: 6

Inspected By: Andrew Russell

Not Inspected Items: 0



DocumentID: NOTI72421

Our Reference: C44584

Generated: 17 May 2021

Building/Location	Item Description/YoM	User Ref	Manufacturer/Serial No.	SWL	Freq of Exam	Next Insp Date	Comment(s)	Client Ref 1	Priority
Even lift Right hand	Electric Passenger/Goods Lift - 10 floors, gearless (2017)		H+C / OE214870.	630 Kg/8 Persons	6	14/11/2021	A - No smoke alarm visible within the motor room - Advise to address A - Suspension and safety gear ropes remain serviceable.	L0154	A, A
Lift motor room	Runway Beam (--)	3217-1	N/K / 3217-1	1000 Kg	12	14/05/2022	S - Serviceable.	L0154	S
Lift motor room	Runway Beam (--)	3217-2	N/K / 3217-2	1000 Kg	12	14/05/2022	S - Serviceable.	L0154	S
Odd Lift Left hand	Electric Passenger/Goods Lift - 10 floors, gearless (2017)	OE214869	H+C / OE214869	630 Kg/8 Persons	6	14/11/2021	A - Suspension and safety gear ropes remain serviceable.	L0154	A
Stairs	Lifting Ring (--)	LP1536	N/K / LP1536	1 T	12	14/05/2022	S - Serviceable.	L0154	S
Stairs	Lifting Ring (--)	LP1338	N/K / LP1338	1 T	12	14/05/2022	S - Serviceable.	L0154	S
Stairs	Lifting Ring (--)	LP1438	N/K / LP1438	1 T	12	14/05/2022	S - Serviceable.	L0154	S
Stairs	Lifting Ring (--)	LP1440	N/K / LP1440	1000 Kg	12	14/05/2022	S - Serviceable.	L0154	S