

Non Domestic Gas Safety Record Certificate

Cert No.

No. 0004

No. Appliances

REGISTER																
Company / Installer						Inspection/Installation Address					Landlord (or agent) Name & Address					
Engineer Company Address Tel No. Gas Safe Reg. ID Card No.	Leyton 3 Brink	194476 3		ham, B34 7JQ	Name Address Postcode Mobile			Paul Da Birkbecl Birming B36 0PC	k House, Guernsey Drive ham	e ,	Name Address Postcode Email Phone		Paul Davies Birkbeck House, Birmingham B36 0PG Paul.Davies@do			
APPLIANCE DETAILS							INSPECTION DETAILS									
										Ī .		Vicual		Ì		

APPLIANCE DETAILS							INSPECTION DETAILS													
	Location	Appliance Type	Make	Model	Flue Type	Appliance serviced	Operating Pressure mBar	Heat Input kW/h	High Combustion Reading		Low Combustion Reading		Safety device(s) correct operation	Ventilation Provision satisfactory	Visual condition of flue and termination satisfactory	Flue Performance test	Appliance Serviced	Appliance safe to use		
									Ratio	CO ppm	CO2 (%)	Ratio	CO ppm	CO2 (%)						
1	Plant Room	Boiler	Potterton	EC Three 170E	RS	Yes	22.1	170	0.0004	27	9.0	0.0006	44	8.8	Yes	Yes	Yes	Pass	Yes	Yes
2	Plant Room	Boiler	Potterton	EC Three 170E	RS	Yes	21.9	170	0.0005	46	9.1	0.0003	31	9.0	Yes	Yes	Yes	Pass	Yes	Yes
3																				
5																				

Defects Identified		Comments					
Defects	None	Comment	Primary circuit losing pressure through water leak on filling				
Labels and Warning Notice Issued	No		loop. Defect reported, materials ordered to rectify water leak.				
Defects	None						
Labels and Warning Notice Issued	No						

Final Checks											
Cylinder/final connection hoses Satisfactory	to LAV/boat	Gas Tightness Satisfactory	Gas Installation pipewor satisfactory	k visual inspection	Equipotential Bondi	Gas Inlet working pre mBars	Gas Inlet working pressure at meter in mBars				
Yes		Yes	Yes		Yes 22.4			Yes			
Signed		Receive	d By		Date		04/12/2020				

NB

Print Name Leyton Brooking Print Name Unoccupied Next inspection Date 03/12/2021