

Summary of Examinations



For Insp Dates: 08/04/2021

To: 08/04/2021

Unserviceable Items: 0

Owner: Solihull Metropolitan Borough Council

Remedial Items: 0

Site ID: Greyfriars House

Advisory Items: 3

Site: Greyfriars House

Serviceable Items: 7

Inspected By: Andrew Russell

Not Inspected Items: 0

Document ID: NOT172390

Our Reference: C44553

Generated: 09 April 2021

Building/Location	Item Description/YoM	User Ref	Manufacturer/Serial No.	SWL	Freq of Exam	Next Insp Date	Comment(s)	Client Ref 1	Priority
LEFT HAND LIFT	ELECTRIC PASSENGER / GOODS LIFT - 8 floors, gearless, fire control. (--)	LIFT No 2	OAKLAND EXCELSIOR / EMR666	630 kg / 8 Persons	6	08/10/2021	A - Last LG5 evidenced in log card as 06/02/17.	L0118	A
Lift Motor Room	Runway Beam (--)		/ JH23193/55	1000 kg	12	08/04/2022	S - Serviceable.	L0118	S
Lift Motor Room	Runway Beam (--)		/ JH23193/56	1000 kg	12	08/04/2022	S - Serviceable.	L0118	S
Lift Motor Room	Runway Beam (--)		/ TJ3251	1000 kg	12	08/04/2022	S - Serviceable.	L0118	S
RIGHT HAND LIFT	ELECTRIC PASSENGER / GOODS LIFT - 8 floors, gearless, fire control. (--)	LIFT No 1	OAKLAND EXCELSIOR / EMR667	630 kg / 8 Persons	6	08/10/2021	A - Last LG5 evidenced in log card as 06/02/17. A - The runby clearance between the counterweight and buffer is minimal - Advise to address	L0118	A, A
Stairs	Lifting eye (--)	TJ3247-2	/ TJ3247-2	1000 kg	12	08/04/2022	S - Serviceable.	L0118	S
Stairs	Lifting eye (--)	TJ3247-3	/ TJ3247-3	1000 kg	12	08/04/2022	S - Serviceable.	L0118	S
Stairs	Lifting eye (--)	TJ3247-4	/ TJ3247-4	1000 kg	12	08/04/2022	S - Serviceable.	L0118	S
Stairs	Lifting eye (--)	TJ3247-1	/ TJ3247-1	1000 kg	12	08/04/2022	S - Serviceable.	L0118	S